

BW DRIVELINE SOLUTIONS

A vehicle's driveline is essential for transferring power from the engine to the wheels. BW's extensive range of high-quality components is designed to resolve common issues quickly and efficiently, keeping vehicles running smoother for longer.

BW has an extensive range of driveline solutions including CV shafts, CV joints, CV boots, centre bearings, rubber couplings, gearbox and differential kits and more.

PRODUCT FEATURES & BENEFITS

- Engineered as direct OE replacements.
- Manufactured using high-quality materials and components.
- Continuously growing range for the Australian and New Zealand market.





1. CV JOINT FAILURES

SIGNS: Clicking during turns or cracked boots leading to grease leaks.

SOLUTION: BW feature premium CV joints and boots, backed by industry-leading warranties. BW offers premium CV joints, center bearings, rubber couplings, transfer kits, and CV boots with industry-leading warranties.

2. FLUID LEAKS

CAUSES: Worn seals or contaminated fluid.

SOLUTION: Regular inspections and high-quality replacement components from BW can prevent damage.

3. VIBRATIONS

CAUSES: Worn universal joints, tail-shaft imbalance, or centre-bearing failure.

SOLUTION: BW offers reliable centre bearings, rubber couplings, and other driveline components built to OE standards.

4. CLUNKING DURING ACCELERATION (Preventative Maintenance Tips)

LUBRICATION: Keep U-joints and CV joints well-greased. **EARLY DETECTION:** Address vibrations, leaks, or clunking promptly to avoid costly repairs.